



**SLING INSPECTION REPORT  
WIRE ROPE, SYNTHETIC, ALLOY CHAIN SLING**

**LARGE MANUFACTURING CO.  
MIDTOWN, AMERICA**

**ATTN: SAFETY MANAGER**

**PERFORMED: SEPTEMBER ~ 2015**

PH# (800) 931-7701



## Commercial Group Lifting Products

12801 UNIVERSAL DR., TAYLOR, MI 48180 \* PH# (734) 947-4000 FAX# (734) 947-4004

September 7, 2015

Large Manufacturing Co.  
Midtown, America

Attn: Safety Department

Attached you will find the results of the lifting survey conducted at your location. All alloy chain slings, wire rope slings, and nylon slings were given a link by link visual inspection and / or tested, as required by OSHA regulations.

Total Items Inspected.....	119
Items Load Tested.....	69
Magna~Flux Tested.....	0
Die Penetrant.....	0
Items Not Inspected.....	0
Items Visual Only.....	57
Items Passed.....	119
Items Failed.....	5

It is my understanding that all repairs are to be sent to and replacements requested from:

COMMERCIAL GROUP LIFTING PRODUCTS  
12801 UNIVERSAL DRIVE  
TAYLOR, MI 48180  
PH# (734) 947-4000 FAX# (734) 947-4004

Attached for your convenience are detailed summaries of the required repairs and/or replacements to bring your facility into compliance with OSHA requirements and ensure safe equipment. Your authorization and purchase order number are necessary before we can proceed. This documentation should be filed with your other OSHA records

This annual inspection was performed in September 2015, as a service of:

COMMERCIAL GROUP LIFTING PRODUCTS, of TAYLOR

Thank you for the opportunity to be of service.

Very Truly Yours

Account Manager

AM / xyz



**COMMERCIAL GROUP  
LIFTING PRODUCTS**

**800-931-7701**

www.cgglift.com

# SLING INSPECTION REPORT SEPTEMBER ~ 2015

Customer Name: **LARGE MANUFACTURING CO.**

BY: **ACCOUNT MANAGER**

INSPECTION DATE	FORM DESCRIPTION	SERIAL#	DESCRIPTION	SIZE CAP	LENGTH LIFT	TYPE	LOCATION	PERFORMED BY	RESULT	COMMENTS	CHIPPED
9/1/2015	Chain Sling Inspection	317-14D	SGG X 1/2IN X 20FT	1/2IN	20FT	SGG	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Chain Sling Inspection	7415	SGG 1/2 in. X 19'6"	1/2IN	19'6"	SGG	GARAGE	INSPECTION TEAM	FAIL	N/A	N
9/1/2015	Chain Sling Inspection	gl721	SGG 5/8 in. X 20ft.	5/8IN	20ft.	SGG	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Chain Sling Inspection	7213	QOSL 9/32 in. X 5ft.	9/21IN	5ft.	QOSL	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Chain Sling Inspection	DC132068	SSS 9/32 in. X 4FT	9/32IN	4ft.	SSS	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Chain Sling Inspection	317-146	SGG X 3/8IN X 8FT	3/8IN	8FT	SGG	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Chain Sling Inspection	317-141	SGG X 3/8IN X 20FT	3/8IN	20FT	SGG	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Synthetic Sling Inspection	106298	EN1902 X 2IN X 12FT	2IN	12FT	EN1-902	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Chain Sling Inspection	GL2670	SGG X 3/8IN X 10FT	3/8IN	10FT	SGG	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Wire Rope Sling Inspection	66749	SWAGED 9/16 in. X 10ft	9/16IN	10ft	WIRE ROPE SLING	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Wire Rope Sling Inspection	66750	SWAGED 9/16 in. X 10ft	9/16IN	10ft	WIRE ROPE SLING	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Wire Rope Sling Inspection	50419	SWAGED 3/8 in. X 8ft	3/8IN	8ft	WIRE ROPE SLING	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Wire Rope Sling Inspection	79613	SWAGED 3/8 in. X 8ft	3/8IN	8ft	WIRE ROPE SLING	GARAGE	INSPECTION TEAM	PASS	N/A	N
9/1/2015	Synthetic Sling Inspection	E106546	EE4904 X 4IN X 6FT	4IN	6FT	EEF4-904	GARAGE	INSPECTION TEAM	PASS	N/A	N